

### Locking Receptacle

**⚠ WARNING:**  
TO AVOID FIRE, SHOCK, OR DEATH, TURN OFF POWER AT CIRCUIT BREAKER OR FUSE AND CHECK THE POWER IS OFF BEFORE WIRING!

**CAUTION:** Use this device only with copper or copper clad wire.

**NOTE:**  
To be installed by a qualified electrician in accordance with national and local electrical codes.

- Strip cable jacket approx. 1.6" (4.0cm).
- Connect grounding wire to green terminal.
- Connect neutral wire to white terminal.
- Connect hot wire to the rest of terminals.
- Tighten torque for screw is 1.6N-m.
- Restore power at circuit breaker or fuse.
- Installation is complete.

### Receptáculo de cierre

**⚠ ADVERTENCIA:**  
PARA EVITAR INCENDIOS, DESCARGAS ELÉCTRICAS O LA MUERTE, CORTE LA CORRIENTE EN EL INTERRUPTOR O EN EL FUSIBLE Y VERIFIQUE QUE NO HAYA ELECTRICIDAD ANTES DE INSTALAR LOS CABLES.

**PRECAUCIÓN:** Utilice este dispositivo solo con cables de cobre o acero recubierto de cobre.

**NOTA:**  
La instalación debe realizarla un electricista calificado de acuerdo con los códigos eléctricos locales y nacionales.

- Pele la cubierta del cable aproximadamente 1.6" (4,0 cm).
- Conecte el cable a tierra a la terminal verde.
- Conecte el cable neutro a la terminal blanca.
- Conecte el cable vivo al resto de las terminales.
- La torsión del tornillo es de 1.6N-m.
- Restablezca la corriente desde el interruptor o el fusible.
- La instalación está completa.